

Carburetor Reference Chart

From White Farm Equipment Parts Bulletin 433378 11/16/84

| OEM Part Number | Marvel Schebler Model | Repair Kit for Marvel Schebler | Replacement Carburetor | Facet Model Number | Repair Kit for Facet Carburetor |
|-----------------|-----------------------|--------------------------------|------------------------|--------------------|---------------------------------|
| 22792 | TSX-399 | 20-7002204 | 20-7002208 | 014997 | 20-7301494 |
| 70337 | TSX-411 | 20-7002204 | 20-7002208 | 014997 | 20-7301494 |
| 116911 | TSX-403 | 30-3046958 | 20-7101076 | 012522 | 35P1446 |
| 117144 | TSX-406 | 30-3046958 | 20-7101076 | 012522 | 35P1446 |
| 117834 | TSX-472 | 30-3046958 | 20-7101076 | 012522 | 35P1446 |
| 120320 | TSX-400 | 30-3046958 | 20-7101076 | 012522 | 35P1446 |
| 135119 | TSX-421 | 30-3046958 | 20-7101076 | 012522 | 35P1446 |
| 151432 | TSX-405 | 30-3046958 | 20-7101076 | 012522 | 35P1446 |
| 101604AS | TSX-755 | 20-7002190 | 20-7101074 | 014991 | 20-7101072 |
| 102631AS | TSX-775 | 20-7002190 | 20-7002207 | 014996 | 20-7101072 |
| 103302AS | TSX-784 | 20-7002190 | 20-7002207 | 014996 | 20-7101072 |
| 104726AS | TSX-807 | 20-7002204 | 20-7002210 | 014999 | 20-7101072 |
| 105730AS | TSX-811 | 20-7002190 | 20-7001074 | 014991 | 20-7101072 |
| 156302AS | USX-29 | 30-3417948 | 20-7002206 | 014990 | 30-3080420 |
| 156304AS | TSX-868 | 20-7002204 | 20-7002210 | 014997 | 20-7301494 |
| 156553AS | USX-32 | 30-3417948 | 20-7002206 | 014990 | 30-3080420 |
| 157582AS | TSX-880 | 20-7002204 | 20-7002100 | 014997 | 20-7301494 |
| 158853AS | USX-37 | 30-3417948 | 20-7002206 | 014990 | 30-3080420 |
| 160928AS | TSX-903 | 20-7002190 | 20-7101074 | 014991 | 20-7101072 |
| 164463AS | TSXU-832 | 30-3046958 | 20-7101076 | 012522 | 35P1446 |
| 164464AS | TSXU-836 | 20-7002190 | 20-7101074 | 014991 | 20-7101072 |
| 164465AS | TSXU-837 | 20-7002204 | 20-7002209 | 014998 | 20-7101072 |
| 164657AS | USX-44 | 30-3417948 | 20-7002206 | 014990 | 30-3080420 |
| 164927AS | TSXU-839 | 20-7002204 | 20-7002208 | 014997 | 20-7301494 |
| 164928AS | TSXU-833 | 30-3046958 | 20-7101076 | 012522 | 35P1446 |
| 164929AS | TSXU-828 | 30-3046958 | 20-7101076 | 012522 | 35P1446 |
| 450426A | TSX-665 | 30-3046958 | 20-7101076 | 012522 | 35P1446 |
| 604808AS | TSX-791 | 20-7002190 | 20-7002207 | 14996 | 20-7101072 |
| 700133AS | TSX-694 | 30-3046958 | 20-7101078 | 012544 | 35P1446 |
| 7AS393 | TSX-499 | 20-7002204 | 20-7002208 | 014997 | 20-7301494 |

| | | | | | |
|------------------------------------|---------|------------|------------|--------|------------|
| 7AS393A | TSX-477 | 20-7002204 | 20-7002208 | 014997 | 20-7301494 |
| 7KS393 | TSX-332 | 30-3046958 | 20-7101074 | 014991 | 20-7101072 |
| AS393F | TSX-168 | 20-7002204 | 20-7002208 | 014997 | 20-7301494 |
| AS393G | TSX-394 | 20-7002204 | 20-7002208 | 014997 | 20-7301494 |
| AS393H | TSX-396 | 20-7002204 | 20-7002208 | 014997 | 20-7301494 |
| BS393K | TSX-186 | 30-3046958 | 20-7101076 | 012522 | 35P1446 |
| EE733 | TSX-30 | 30-3046958 | 20-7101076 | 012522 | 35P1446 |
| EE733A | TSX-36 | 30-3046958 | 20-7101076 | 012522 | 35P1446 |
| HS393A | TSX-120 | 30-3046958 | 20-7101076 | 012522 | 35P1446 |
| HS393B | TSX-138 | 30-3046958 | 20-7101076 | 012522 | 35P1446 |
| KE817P | TSX-67 | 20-7002204 | 20-7002210 | 014999 | 20-7101072 |
| KS393 | TSX-181 | 20-7002190 | 20-7101074 | 014991 | 20-7101072 |
| KS393A | TSX-221 | 20-7002190 | 20-7002207 | 014996 | 20-7101072 |
| KS393B | TSX-374 | 20-7002190 | 20-7101074 | 014991 | 20-7101072 |
| KS393C | TSX-610 | 20-7002170 | 20-7101074 | 014991 | 20-7101072 |
| LE806 | TSX-68 | 20-7002204 | 20-7002208 | 014997 | 20-7301494 |
| LS393A | TSX-418 | 30-3046958 | 20-7101076 | 012522 | 35P1446 |
| AG PARTS FIRST, LLC (330) 264-9720 | | | | | |
| LS393B | TSX-603 | 30-3046958 | 20-7101078 | 012544 | 35P1446 |
| MS393 | TSX-363 | 30-3046958 | 20-7101076 | 012522 | 35P1446 |
| MS393A | TSX-380 | 30-3046958 | 20-7101076 | 012522 | 35P1446 |
| RE733C | TSX-97 | 20-7002190 | 20-7101074 | 014991 | 20-7101072 |
| 10A524 | TSX-360 | 20-7002190 | 20-7101074 | 014991 | 20-7101072 |
| 10A1329 | TSX-231 | 30-3046958 | 20-7101076 | 012522 | 35P1446 |
| 10A2944 | TSX-497 | 30-3046958 | 20-7101078 | 012544 | 35P1446 |
| 10A6268 | TSX-625 | 20-7002204 | 20-7002208 | 014997 | 20-7301494 |
| 10A6269 | TSX-624 | 20-7002204 | 20-7002210 | 014999 | 20-7101072 |
| 10A6464 | TSX-633 | 20-7002190 | 20-7101074 | 014991 | 20-7101072 |
| 10A8333 | TSX-650 | 30-3046958 | 20-7101077 | 012566 | 35P1446 |
| 10A10055 | TSX-693 | 20-7002204 | 20-7002208 | 014997 | 20-7301494 |
| 10A11451 | TSX-714 | 30-3046958 | 20-7101077 | 012566 | 35P1446 |
| 10A11452 | TSX-713 | 20-7002190 | 20-7101074 | 014991 | 20-7101072 |
| 10A12283 | TSX-740 | 20-7002205 | 20-7002208 | 014997 | 20-7301494 |
| 10A15157 | TSX-795 | 20-7002205 | 20-7002210 | 014999 | 20-7101072 |

| | | | | | |
|------------|----------|------------|------------|--------|------------|
| 10A15430 | TSX-797 | 20-7002190 | 20-7101074 | 014991 | 20-7101072 |
| 10A15562 | TSX-814 | 20-7002190 | 20-7101074 | 014991 | 20-7101072 |
| 10A16902 | TSX-825 | 20-7002190 | 20-7101074 | 014991 | 20-7101072 |
| 10A18173 | TSX-878 | 20-7002190 | 20-7002210 | 014996 | 20-7101072 |
| 10A21577 | USX-40 | 30-3417948 | 20-7002206 | 014990 | 30-3080420 |
| 10A22717 | TSX-901 | 20-7002205 | 20-7002210 | 014997 | 20-7301494 |
| 10A23732 | TSX-917 | 20-7002190 | 20-7002207 | 014996 | 20-7101072 |
| 10A25103 | USX-43 | 30-3417948 | 20-7002206 | 014990 | 30-3080420 |
| 15A4319 | TSX-364 | 20-7002204 | 20-7002210 | 014999 | 20-7101072 |
| 15A8955 | TSX-607 | 20-7002204 | 20-7002210 | 014999 | 20-7101072 |
| 15A9253 | TSX-604 | 20-7002204 | 20-7002210 | 014999 | 20-7101072 |
| 20-7001457 | TSXU-963 | 20-7002190 | 20-7101075 | 014992 | 20-7101072 |
| 30-3032787 | TSXU-838 | 20-7002204 | 20-7101075 | 014992 | 20-7101072 |
| 35A5135 | TSX-862 | 30-3046958 | 20-7101078 | 012544 | 35P1446 |
| | | | | | |
| | | | | | |

We have attempted to insure the accuracy of the information listed and reserved the right for type errors.
Some part numbers are strictly for reference purpose only